

# Welding Burns 101

- Wear approved welding helmets.
- Wear safety goggles or glasses – even under a helmet.
- Clearly mark hot work areas.
- Remove any combustible items.



**Safety+Health**

The Official Magazine of the NSC Congress & Expo